


COLLIER SPRINKLER

No. d'article	plage de serr. mm	pouce	manchon	matériau	Prix/pce.	
278.2001	20 – 23	1/2	M8	25 x 3,0	2.80	1
278.2002	25 – 29	3/4	M8	25 x 3,0	2.80	1
278.2003	30 – 35	1	M8	25 x 3,0	2.40	1
278.2004	41 – 46	1 1/4	M8	25 x 3,0	2.50	1
278.2005	48 – 55	1 1/2	M8	25 x 3,0	2.50	1
278.2006	57 – 61	2	M8	25 x 3,0	2.60	1
278.2008	25 – 28	3/4	M10	25 x 3,0	3.20	1
278.2009	32 – 35	1	M10	25 x 3,0	3.20	1
278.2010	41 – 46	1 1/4	M10	25 x 3,0	3.20	1
278.2011	48 – 55	1 1/2	M10	25 x 3,0	3.20	1
278.2012	57 – 61	2	M10	25 x 3,0	3.20	1
278.2013	76	2 1/2	M10	30 x 3,0	3.40	1
278.2014	89	3	M10	30 x 3,0	4.80	1
278.2015	108		M10	30 x 3,0	5.20	1
278.2016	114	4	M10	30 x 3,0	5.20	1
278.2017	133		M12	30 x 3,0	6.10	1
278.2018	140	5	M12	30 x 3,0	6.20	1
278.2019	159		M12	30 x 3,0	7.00	1
278.2020	165	6	M12	30 x 3,0	7.20	1
278.2021	168		M12	30 x 3,0	7.20	1
278.2022	219	8	M16	50 x 5,0	9.70	1



Agréé après les nouvelle directives VDS d'installation de gicleurs d'incendie (VDS 2092, planification et installation).

tous les prix sont nets, en FRS, sans TVA